



Certificate of Analysis

Productname: Chlorhexidini digluconat. sol.

Inspection No: 108827/1221/536
Batchnumber: 21A27-T08-091236
Expiration date: 31.08.2023
Analysed according to: ČL 2017-Dopl.2018, Ph.Eur.10.0
Original Manuf. Date: 28.9.2020

Sample Unit: 1 x 25 ml
Batch Size: 10 x 1 l

Identification of producer: V00572
Batch no. of vendor: B/136/20

	Requirement	Result	Unit	Standard remark	Insp. Site
CHARACTERS					
Appearance	Almost colourless or pale-yellowish liquid.	Conform			Fagron CZ
Solubility	Conform	Conform			Fagron CZ
IDENTIFICATION					
Identification A	Conform	Conform		IR-spectrum	Fagron CZ
Identification B	Conform	Conform		TLC	Fagron CZ
TESTS					
Relative density	1,06 - 1,07	1,07			Fagron CZ
pH	5,5 - 7,0	6,2			Fagron CZ
Impurity P-Chloroaniline	<= 500	200	µg/g		Fagron CZ
Related substances	Conform	Conform		HPLC	Contract Lab
Impurity N	<= 1,0	<1,0	%		Contract Lab
Impurity H	<= 0,5	<0,5	%		Contract Lab
Impurity A	<= 0,4	<0,05	%		Contract Lab
Impurity J	<= 0,4	<0,4	%		Contract Lab
Impurity K	<= 0,4	<0,4	%		Contract Lab
Sum of impurities I and O	<= 0,4	<0,05	%		Contract Lab
Impurity G	<= 0,3	<0,3	%		Contract Lab
Impurity B	<= 0,2	<0,2	%		Contract Lab
Impurity F	<= 0,2	<0,05	%		Contract Lab
Impurity L	<= 0,2	<0,2	%		Contract Lab
Impurity Q	<= 0,2	<0,2	%		Contract Lab
Unspecified impurities	<= 0,10	<0,10	%		Contract Lab
Total impurities	<= 3,0	<3,0	%		Contract Lab
Microbiology	Conform	Conform			Contract Lab
TAMC	<= 2 x 10 ³	Conform	CFU/g		Contract Lab
TYMC	<= 2 x 10 ²	Conform	CFU/g		Contract Lab
TSE/BSE	No contamination with TSE/BSE-risk materials.	Conform			Data Producer
Residual solvents	CPMP/ICH/82 260/2006	Conform			Data Producer
Metallic residues	ICH Q3D on elemental impurities	Conform			Data Producer
ASSAY					
Chlorohexidine digluconate	190 - 210	207	g/l		Contract Lab
Chlorohexidine digluconate	178 - 198	193	g/kg		Contract Lab

Name	Fagron a.s. (CZ)	Address	Holická 1098/31m, Olomouc	Phone No.	+420585222590
	Kontrolní laboratoř č. 536	Post Code	779 00	Fax No.	+420 585 226 521

Performed by: Lucie Kubáňová DiS.
Responsible: Ing. Pavel Mišák, QC
MVDr. Zdenka Borská, QA
Date: 10.12.2021
Conclusion: **APPROVED**

This document has been produced electronically from our quality system and is valid without signature.

Name	Fagron a.s. (CZ) Kontrolní laboratoř č. 536	Address	Holická 1098/31m, Olomouc	Phone No.	+420585222590
		Post Code	779 00	Fax No.	+420 585 226 521